| FORM NO. MAY 1949 | 51.01 | CLASSIFICATION 5 | ECRET/CONTROL US OFFICIA | TR ONTA | 50X1-HUM |
|--|-------------------|---|--------------------------|-------------------------------|-------------------|
| | | CENTRAL IN | NTELLIGENCE AGENCY | REPORT | |
| | | INFORMA | TION REPORT | CD NO. | |
| OUNTRY | USSR (Bla | ck Sea) | | DATE DISTR. | 14 September 1950 |
| JBJECT | Ports of | Odessa, Nikolayev, a | and Novorossiisk | NO. OF PAGES | 1 |
| ACE CQUIRED | | | | NO. OF ENCLS. | 3 |
| ATE OF | | | | SUPPLEMENT TO | 50X1-HU |
| AIS DOCUMENT C F THE UNITED S S C. 31 AND 3 | STATES WITHIN THE | IN AFFECTING THE NATIONAL DEFENSE MEANING OF THE ESPIONAGE ACT SO S TRANSMISSION OR THE REVELATION AN UNAUTHORIZED PERSON IS PRO- THIS FORM IS PROHIBITED | THIS IS UNEV | REPORT NO. ALUATED INFORMATI | ON 50X1-HUM |
| F THE UNITED S | STATES WITHIN THE | MEANING OF THE ESPIONAGE ACT 50 | THIS IS UNEV | | |
| HIS DOCUMENT C F THE UNITED S S. C. 31 AND 3 | STATES WITHIN THE | MEANING OF THE ESPIONAGE ACT 50 | THIS IS UNEV | ALUATED INFORMATI | |
| HIS DOCUMENT C F THE UNITED S S C . 31 AND S | STATES WITHIN THE | MEANING OF THE ESPIONAGE ACT 50 | | ALUATED INFORMATI | |
| HIS DOCUMENT C | STATES WITHIN THE | MEANING OF THE ESPIONAGE ACT 50 | | ALUATED INFORMATI | |
| AIS DOCUMENT C F THE UNITED S S C. 31 AND 3 | STATES WITHIN THE | MEANING OF THE ESPIONAGE ACT 50 | | ALUATED INFORMATI | |

CLASSIFICATION SECRET/CONTROL US OFFICIALS ONLY

| STATE | NAVY | х | NSRB | DISTRIBUTION | |
|-------|------|---|------|--------------|--|
| ARMY | AIR | | | | |

| accific | ed in Part - Sanitized Copy Approved for Release 2012/03/15 : CIA-RDP83-00415R00610008000 | 50X1-HU |
|---------|--|---------------|
| 355IIIE | ad in Part - Samilized Copy Approved for Release 2012/03/13 . CIA-RDF63-00413R00610006000 | 0-9 |
| | | |
| | | |
| | | |
| | | |
| | | |
| | 2. Naval Vessels | |
| | the mine-field outside of | 50X1-H |
| | Odessa had been removed. three mine-sweepers | _50X1-H |
| | were sweeping the area. These were towing cables which led to believe that they were sweeping for magnetic mines. They were followed | 50X1-H |
| | by a fourth vessel. | 30X1-11 |
| | four submarines were observed leaving | 50X1-H |
| | the harbor every morning, returning the same evening. After a careful study | |
| | of the "Swedish Naval Calendar" of 1949, identified these as the M 89 type. | 50X1-H |
| | 3. Nikolaev, 7-14 April 1950 | |
| | Name of the second of the seco | |
| | The old grain elevator is no | _ 50X1-H |
| L | longer in use. | 30X1-II |
| | Between the two grain elevators was located the pilot station, and nearby | |
| | were the officer of the INFIOT agency, and EXPORTKLES. | |
| | | |
| | The main dock is that one in front of the old grain elevator. It is constructed of earth and concrete. Its average height above the water was seven | |
| | feet. Along this dock was one Russian "Liberty" ship unloading, in | |
| | addition to 2 or 3 smaller vessels. East of this dock, for a distance of a few hundred yards, was an area where no docks have been constructed (6, 7 and | 50X1-H |
| | 8, Attachment 1). | |
| | • | ⁻50X1-H |

| The height of this dock was a pproximately |
|--|
| 7 feet. During the war this dock must have suffered bomb damage as its |
| eastern section had collapsed. A vessel, of the "Liberty" type, was |
| docked nearby. Further east was another section of the harbor where no docks |
| have been constructed. Here were several piles of scrap iron which resembled |
| the remains of old derricks (9-19 Attachment 1). |

50X1-HUM

50X1-HUM

4. Harbor Installations in Nikolaev

The main dock was equipped with five electric cranes on rails. Three of these were of the swivelling type and had an estimated capacity of 4 tons. The other two appeared to be of heavier construction, and were equipped with coal buckets. There were a series of railroad tracks on the dock. Near the new grain elevator was a set of tracks leading to the elevator, and behind this appeared a second set of tracks; both of these, instead of being set into the concrete of the dock, were simply laid on the dock.

The new grain elevator, which suffered only slight damage during the war, was constructed in 1930. It drops grain straight into the holds where trimming is performed by hand.

The main dock pequipped with electric installations but had no facilities for providing water.

A number of cranes were observed in that section of the docks shown as "Pantent Slipper" (Attachment 1).

No floating cranes or dry-docks were observed anywhere in the harbor.

5. Harbor Vessels

Numerous oil barges were observed in the harbor. Most of these were constructed of steel and must have displaced about 1500 tons. Eight of these were tied up at a point one nautical mile from the shore. From time to time these were shifted from one point to another. Oil barges were also tied up at the oil dock and Kabotazhni breakwater. Two large tugs, of approximately 500 tons, were used for most of the towing of the barges.

50X1-HUM

6. Naval Vessels


Two small naval vessels about 50 feet in length, possibly tugs, were observed in the harbor. These were used to guard foreign vessels at anchor outside the harbor.

| Declassified in Part | Sanitized Conv | Approved for Release | 2012/03/15 - 01/ | \ DDD83 00/15D | 006100080006.0 |
|------------------------|----------------|----------------------|----------------------|-----------------|----------------|
| Declassified in Part - | | Approved for Release | : 20 12/03/ 13 . GIF | 1-KDP03-UU4 ISK | <u> </u> |

| 7• | Security Control | |
|------|--|--------|
| por | Security precautions were as strict and thorough as found in most Soviet ts. | • 50X² |
| | whole harbor area was heavily patrolled and guarded. River Bug | |
| | At the northern end of Kinburn Spit was observed the wreck of a vessel of roximately 3000 tons. A light had been mounted on the wreck. | |
| Rive | the maximum draft allowed for vessels in the er Bug was 24 feet. | |
| · 44 | | |

50X1-HUM

CONTROL U. S. OFFICIALS ONLY



| | | | • Nikolatev |
|---|---|--|---------------------------------------|
| my many leaded empty of the old oils. The piecewood on old it was notte | | This material procured by Central In ellipance Agency | The entire harbor area was destroyed; |
| seemed to be no proper planning. | 5 | | seemed to be no proper planning. |

Declassified in Part - Sanitized Copy Approved for Release 2012/03/15 : CIA-RDP83-00415R006100080006-9

CONTROL

An unknown number of wrecks were noted in the northeastern section of the harbor (A, Attachment 2). The four most northerly docks were destroyed


Novorossisk Harbor


Classification

50X1-HUM

| and not in use. They were not being repaired | 50X1-HU |
|--|---------|
| dock No. 5 (see Attachment 2) was constructed of concrete, and measured 400 meters. Depth of the water six feet from the dock was 30 feet. A railroad extended along the length of this dock. | |
| The grain elevator (B, Attachment 2) was located a short distance from the dock. Grain was brought from the elevator to the dockside on a conveyor. Approximately 1000 tons of grain were leaded in 24 hours. | |
| Dock No. 6 was being repaired. Divers were observed working in the area. this dock would be constructed of concrete. | 50X1-HU |
| At No. 7 dock a Russian tanker was unloading. This appeared to be a lengthy process | 50X1-HU |
| To the west of the grain elevator were observed a number of oil storage tanks. Their number and size is unknown. (D, Attachment 2) | |
| There was very little activity at the southernmost dock (8. Attachment 2). | 50X1-HU |
| There were no signs of either shipbuilding or repair work. There was little harbor traffic. Only one tug and a number of old barges were seen. The barges appeared in poor condition. In contrast to Nikolaiev, the administration of the port appeared good. | |
| 5. Military Information | |
| Constant tank maneuvers were observed in an area south of the town (E, Attachment 1). Though the size and type of the tanks could not be made out, it appeared as if they were being tested in mud and soft terrain. | |
| a destroyer or corvette entered the harbor only to turn and leave almost at once. This vessel had two turrets forward, each with a single gun. The mast was placed directly aft of the bridge structure. One stack was set at a considerable angle. An unknown number of small patrol craft were observed in the harbor. These were equipped with anti-aircraft guns forward and depth charges positioned on the poop. They appeared to be of heavy construction. The bridge structure on these craft was of the open type. It was impossible to estimate their speed. | 50X1-HU |







Declassified in Part - Sanitized Copy Approved for Release 2012/03/15 : CIA-RDP83-00415R006100080006-9

| 2. The four northernmost docks (1, 2, 3 and 4, Attachment I) were destroyed. No repair work was under way | 50X1-HU |
|---|---------|
| the arrival of a Russian vessel was given priority | |
| the maximum loading capacity was | 50X1-HU |
| Iength of the grain dock was between 350-400 meters. Depth of the water alongside the dock was about 30 feet. | 50X1-HL |
| 72 U.S. 1134US GROUP COST 1135 COST | 50X1-HU |
| 3. There were no indications of repair work being carried out in any of the dock areas. | |
| There was some activity in the shippard in the northeast section of | |

There was some activity in the shippard in the northeast section of the harbor. A small vessel was on the ways.

In the mountains to the northeast of the harbor, blasting work was in progress. A number of railroad cars were observed emerging from two tunnels. During the night lights were seen in this area. There appeared to be some concrete construction here, though it was difficult to be certain of the type of construction. Due north of this area (Y, Attachment 2) were two small oil storage tanks.

- approximately 4,000 tons dw.

 and a vessel of unknown tonnage that was loading grain. There were two tugs in the harbor, one somewhat larger than the other.
 - 5. Two motor torpedo boats visited the harbor daily. They showed a

Classification

This material procured by Central In elligence Agency 50X1-HUM

50X1-HUM



Declassified in Part - Sanitized Copy Approved for Release 2012/03/15 : CIA-RDP83-00415R006100080006-9

speed of approximately 40 knots. A patrol boat followed ships in and out of the harbor. This was described as a small open motor boat with a small gun forward.

